



MS3711A



Pin Assignment

Pin NO.	Signal Name
1	P (+)
2	N (-)
	POWER
⏏	GND
4	+ OUTPUT 1
5	- OUTPUT 1
6	N. C.
7	+ OUTPUT 2
8	- OUTPUT 2
9	+ INPUT
10	- INPUT
11	N. C.

Pin Location



単位: mm