



MS3770



Pin Assignment

Pin NO.	Signal Name
1	P(+) POWER
2	N(-)
3	GND
4	+ OUTPUT 1
5	- OUTPUT 1
6	N.C.
7	+ OUTPUT 2
8	- OUTPUT 2
9	+ INPUT
10	- INPUT
11	N.C.

Pin Location



単位:mm